

MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY

COMMITTE ALCOHOL PROGRAM

DATAMASTER MAINTENANCE REPORT

assista.		0.01) O Of
Complete this report in duplicate at the time of the is repaired. Send copy to Department of Health; retain	regular monthly preventive mainten original in department file.	ance check, and whenever instrument
DATAMASTER SN 204063 /INV#127196	1/	DATE OF INSPECTION
	,	6-5-269
MARIES COUNTY SHEPIFE'S DEPT	VIENNA, MO	I'ME OF INSPECTION
LOCATION OF INSTRUMENT (STREET AND CITY) MARIES COUNTY SHEPIFF'S DEPT CHECKLIST: Place a check (<) to the left of each iter in observed values where determined.) Unchecked item	m if found to be satisfactory or if opens must be corrected before using ins	erating within established limits. (Write trument.
D DIAGNOSTIC CHECK (PRINTOUT ATTACHED)	<u> </u>	
□ СОМРИТЕЯ	DETECTOR	
PROGRAM	[] FILTERS	
HEATERS SAMPLE CHAMBER 50°C	QUARTZ STANDARD	
☑ FLOW DETECTOR	LY CALIBRATION	
PUMP HIGH SPEED	PRINTER	
☑ INDICATOR LIGHTS OK		
TIME AND DATE 0255 /06-05-09		1000
\square SIMULATOR TEMPERATURE (34 °C ± 0.2°C) \square	-4771 34 C S. N. 66-66	12 34.1°C OKA/
CALIBRATION CHECK - PASSED		1
Run three tests using a standard solution. All th	ree tests must be within ± 5% of t	he standard value and must have a
spread of .005 or less. Check the box correspond	ing to the standard solution being ú	sed. (PRINTOUT ATTACHED) (USE
RECIFICULATION PUMP)		
☑ 0.100% STANDARD - MUST READ BETWEEN 0 ☐ 0.040% STANDARD - MUST READ BETWEEN 0		
(ONLY ONE STANDARD IS TO BE USED PER MA		
TEST 1 . 096 TEST 2		ST3 . 097
PERFORM R.F.I. TEST (PRINTOUT ATTACHED)		
NUMBER OF REFUSALS, SINCE LAST MAINTENAI FOLLOWS: (DO NOT INCLUDE SIMULATOR TES	NCE REPORT, AND NUMBER OF BE	BEATH TESTS IN EACH RANGE AS
REFUSALS Ø (004) Ø (.0509) Ø) (.1014) ∂ (.15 ⁻	9) Ø (Over .19)
ist any new parts and describe any alteration or modi	ification that was made to restore th	e instrument to operate satisfactorily
ind within established limits (use other side if necessary <u>Cuth LABORATORIES</u> (NC	·)	•
EXP DATE: 7-14-2009 BUT #: 7		
		-
		-
NSPECTING OFFICER		
PR. (20-22) 4997	2997 PRINT NAME TROOPER B.A. VOGT #997	
YPE II PERMIT NUMBER/EXPIRATION DATE	TELEPHONE NUMBER	
920091 / 04.22-2011	(573) 368-2345	V. T.
) 580-1468 (9-94)	007: HUTWIE	



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 08240 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1221 percent (w/vol) ethyl alcohol. The expiration date for this lot number is July 14, 2009 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.10 percent BAC.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

Face This Side Down – This Edge In First

BAC DataMasterEvidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204063 86/85/89

TESTING OFFICER:
VOGT/BROCK/A
OFFICER 1.D.: 997
PERMIT NUMBER: 92009)
EXPIRATION DATE: 04/22/1)
MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---

BLAME TEST	, god	10:09
INTERNAL STAMBARD	VERIFIED	18:09
EXTERNAL STANDARD	. 096	
BLAMK TEST	` . Ø90 _.	1070
EXTERNAL STANDARD .	. 897	19:11
BLANK TEST	. 990	18:11
EXTERNAL STANDARD	, 997	io: is
BLANK TEST	. 990	18512

] ||SIM. = .1 |AVG. = .0966 Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

MISSOUR) STATE HIGHWAY PATROL BAC DATAWASTER SERIAL NUMBER 004063 06/05/09

ARREST TIME: 09:45
SUBJECT NAME:
VOGT/BROCK
DOB: 01/84/84
SEX: M
STATE/D.L.: XX/XXXXX
ARRESTING OFFICER:
VOOT/BROCK/M
OFFICER 1.D.: 997
TESTING OFFICER:
VOGT/BROCK/R
OFFICER 1.D.: 997
PERMIT NUMBER: 920091
EXPIRATION DATE: 04/22/11
MISCELLAMEOUS DATA:

-- BREFITH FMALYSIS ---

BLANK TEST .000 10:15 INTERNAL STANDARD VERIFTED 10:16 RADIO INTERFERENCE

Operator Signature 1977

2208-02

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 20406S 06/05/09 09:55

-- DIRGNOSTIC CHECK ---

COMPUTERS

OKAY

PROGRAM:, .

OKHY

HERTERS

SAMPLE CHAMBER:

56.

FLOW DETECTORS

OKAY

PUMP

HIGH SPEED:

OKIHY

DETECTORS

OKAY

FILTERSA

.....

QUARTZ STAMBARBE

OKAY OKAY

CALIBRATION:

 $\mathbb{Q}[(T]')$

PRINTER TEST

!"##%%:()#+,-./0123456789:(<=>?@ABCDEF6 HIUKLMMOP@RSTUVWXYZE\I^_ abodefghijklmno pqrstuvwxqz{I>*

Operator Signature

2208-02

State of Missouri DEPARTMENT OF HEALTH



MO 580-0771 (7-88)

PERMIT TYPE II



Lab. 4 (R7-88)

BROCK A VOGT

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):					
DATAMASTER					
for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.					
Date	04/22/09	John of Mathewson			
Number	000001	Director of State Public Health Laboratory			
Expires 04/22/2011	Masgard T. Barnelly Director, Department of Health				